

State of California—Health and Welfare Agency  
Form Approved OMB No. 2050-0039 (Expires 9-30-86)

Please print or type. (Form designed for use on elite (12-pitch typewriter).

Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

### UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.		Manifest Document No.		2. Page 1 1 of 1		Information in the shaded areas is not required by Federal law.	
C A D 0 6 7 7 3 7 2 2 1		0 1 0 1 0 1 3 1 6		A. State Manifest Document Number		87113406	
3. Generator's Name and Mailing Address <b>SIERRACIN TRANSFLEX</b> 5600 BANDINI BLVD., BELL, CA. 90201		6. US EPA ID Number <b>C A D 0 6 7 7 3 7 2 2 1</b>		B. State Generator's ID		903100	
4. Generator's Phone (213) 269-9100		7. Transporter 1 Company Name <i>Vanuatu Rogers</i>		C. State Transporter's ID		D. Transporter's Phone	
5. Transporter 1 Company Name		8. US EPA ID Number <b>C A D 0 6 7 7 3 7 2 2 1</b>		E. State Transporter's ID		F. Transporter's Phone	
9. Designated Facility Name and Site Address <b>OMEGA CHEMICAL COMPANY</b> 12504 E. WHITTIER BLVD., WHITTIER, CA. 90602		10. US EPA ID Number <b>C A D 0 4 2 2 4 5 0 0 1</b>		G. State Facility's ID		<b>C A D 0 4 2 2 4 5 0 0 1</b>	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) a. WASTE TETRACHLOROETHYLENE ORM-A UN1897		12. Containers No. Type		13. Total Quantity		14. Unit Wt/Vol	
		0 0 15 D I M		0 1 0 1 2 1 7 1 5		G	
b.							
c.							
d.							
J. Additional Descriptions for Materials Listed Above <b>WASTE TETRACHLOROETHYLENE</b>		K. Handling Codes for Wastes Listed Above a. 01/F002 01		b.		c. d.	

### 15. Special Handling Instructions and Additional Information

GLOVES AND GOGGLES

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

John A. McVay

Signature

Month Day Year  
0 9 1 6 8 7

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Frank Areiola

Signature

Month Day Year  
10 9 1 6 8 7

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year  
10 9 1 6 8 7

19. Discrepancy Indication Space

State of California - Health and Welfare Agency  
Form Approved OMB No. 2050-0039 (Expires 9-30-88)  
Please print or type. (Form designed for use on disk (12-pitch typewriter).

Department of Health Services,  
Toxic Substances Control Division,  
Sacramento, California

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>C A D 9 8 2   3 5 6 9 3 3   0 1 8 1 1 C</b>	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address <b>SIERRACIN TRANSFLEX 5600 BANDINI BLVD., BELL, CA. 90201</b>				A. State Manifest Document No. <b>87113415</b>			
4. Generator's Phone (213) 269-9100				B. State Generator's ID <b>H A H 0 3 6 0 0 9 5 1 8</b>			
5. Transporter 1 Company Name <b>VAN WALTERS &amp; ROGERS</b>		6. US EPA ID Number <b>K A P 0 0 9 2 3 0 2 4 4</b>	7. Transporter 2 Company Name	D. Transporter's Phone <b>260-5217</b>	E. State Transporter's ID <b>804025</b>	F. Transporter's Phone	
8. US EPA ID Number				G. State Facility's ID <b>C A D 0 4 2 2 4 5   0 0 1</b>	H. Facility's Phone <b>213-698-0991</b>		
9. Designated Facility Name and Site Address <b>OMEGA CHEMICAL CO. 12504 E. WHITTIER BLVD. WHITTIER, CA. 90602</b>		10. US EPA ID Number <b>C A D 0 4 2 2 4 5   0 0 1</b>	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) <b>a. FREON - HAZARDOUS WASTE LIQUID N.O.S. ORM-A UN1693</b>	12. Container No. <b>1</b>	13. Total Quantity <b>11510 G</b>	14. Unit Wt/Vol <b>b. 211</b>	15. Waste No. <b>EPA/Other</b>
			<b>b.</b>	<b>3 D M</b>			<b>State</b>
			<b>c.</b>	<b>1</b>			<b>EPA/Other</b>
			<b>d.</b>	<b>1</b>			<b>State</b>
				<b>1</b>			<b>EPA/Other</b>
J. Additional Descriptions for Materials Listed Above <b>FLOROCARBON 55 - 65% ETHANOL 30 - 35% SOLDER FLUX 5 - 10%</b>				K. Handling Codes for Wastes Listed Above <b>a. b. c. d.</b>			
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.							
Printed/Typed Name <b>JOHN A. McVAY</b>		Signature <i>JAMCvay</i>		Month Day Year <b>10/19/1988</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>MICHAEL STEVENSON</b>		Signature <i>michael Stevenson</i>		Month Day Year <b>10/21/1988</b>			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year			
19. Discrepancy Indication Space				Month Day Year			
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>Henry R. Solomon</b>							

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No <b>C A D 9 8 2 3 5 6 9 3 3</b>	Manifest Document No <b>August</b>	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>SIERRACIN TRANSFLEX</b> <b>5600 BANDINI BLVD., BELL CA 90201</b>		A. State Manifest Document Number <b>87113498</b>				
4. Generator's Phone (213) 269-9100		B. State Generator's ID <b>H A H Q 3 6 0 0 9 5 1 8</b>				
5. Transporter 1 Company Name <b>VAN WATER &amp; ROGERS</b>		C. State Transporter's ID <b>905445</b>				
6. Transporter 1 US EPA ID Number <b>C A D 0 5 5 0 0 0 5 2 4 6</b>		D. Transporter's Phone (213) 260-5117				
7. Transporter 2 Company Name		E. State Transporter's ID				
8. Transporter 2 US EPA ID Number <b>1087445</b>		F. Transporter's Phone				
9. Designated Facility Name and Site Address <b>OMEGA CHEMICAL COL</b> <b>12504 E. WHITTIER BLVD.,</b> <b>WHITTIER, CA 90602</b>		G. State Facility's ID <b>CAD10H224501011</b>				
10. US EPA ID Number <b>C A D 0 4 2 2 4 5 0 0</b>		H. Facility's Phone <b>(213) 698-0991</b>				
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	L Waste No.
a. FREON - HAZARDOUS WASTE LIQUID N.O.S. ORM-A UN 1693		0 0 3	D M	1 5 0	G	State 21-1
b.		1 1	1	1 1 1		EPA/Other Food
c.		1 1	1	1 1 1		State
d.		1 1	1	1 1 1		EPA/Other
J. Additional Descriptions for Materials Listed Above <b>FLOROCARBON 55-65%</b> <b>ETHANOL 30-35%</b> <b>SOLDER FLUX 5-10%</b>		K. Handling Codes for Wastea Listed Above a. b.				
15. Special Handling Instructions and Additional Information						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>John McVay</b>		Signature <i>John McVay</i>		Month Day Year <b>07 01 88</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>MICHAEL STEVENSON</b>		Signature <i>Michael Stevenson</i>		Month Day Year <b>10/31/88</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>John HALCE</b>		Signature <i>John HALCE</i>		Month Day Year <b>1/24/88</b>		

II CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802. WITHIN CALIFORNIA CALL 1-800-852-7550

TRANSPORTER

FACILITY

04/15/88

Shipper 15250

Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>C A D 98 13 9 6 97 1</b>	Manifest Document No.	2. Page 1 of 2	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>Serracin Magnedyne 2258 Rutherford Rd., Carlsbad, CA 92008</b>		A. State Manifest Document Number <b>87118723</b>				
4. Generator's Phone (619) 438-3321		B. State Generator ID				
5. Transporter 1 Company Name <b>Omega Recovery Services</b>		6. US EPA ID Number <b>C A D 04 2 24 5 001</b>	C. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number <b>C A D 04 2 245 001</b>	D. Transporter's Phone <b>213/698-0991</b>			
9. Designated Facility Name and Site Address <b>Omega Recovery Services 12512 E. Whittier Blvd. Whittier, CA 90602</b>		10. US EPA ID Number <b>C A D 04 2 245 001</b>	E. State Transporter's ID			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	L Waste No.	
a. Hazardous Waste Liquid NOS NA 9189 (Fluorosolv TF)		0 0 5 DM	12106	R	State EPA/Other	
b. Waste Methylene Chloride ORM-A UN 1593		0 0 3 DM	11010	G	State EPA/Other	
c. Waste Acetone UN 1090 Flammable Liquid		0 0 1 DM	1510	G	State EPA/Other	
d. Waste Isopropyl Alcohol UN 1219 Flammable Liquid		0 0 1 DM	510	G	State EPA/Other	
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above a. 01 b. 01 c. 01 d. 01				
15. Special Handling Instructions and Additional Information						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>STEVEN PENNINGTON</b>		Signature <i>Steven Pennington</i>		Month Day Year <b>10/4/27/88</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name <b>JAVIER HERVANDEZ</b>		Signature <i>Javier Hernandez</i>		Month Day Year <b>04/27/88</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name <b>FRANK FORD</b>		Signature <i>Frank Ford</i>		Month Day Year <b>10/4/27/88</b>		

Please print or type. (Form designed to use on elite (12-pitch typewriter).

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CA D 9 8 13 96 9 71</b>	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address <b>Serracin Magnedyne 2258 Rutherford Road, Carlsbad, CA 92008</b>						A. State Manifest Document Number <b>87118737</b>	
4. Generator's Phone (619) 438-3321						B. State Generator's ID	
5. Transporter 1 Company Name <b>Omega Recovery Services</b>		6. US EPA ID Number <b>C A D 0 4 2 245 001</b>					C. State Transporter's ID
7. Transporter 2 Company Name		8. US EPA ID Number					D. Transporter's Phone <b>213/698-0991</b>
9. Designated Facility Name and Site Address <b>Omega Recovery Services 12512 E. Whittier Blvd. Whittier, CA 90602</b>		10. US EPA ID Number <b>C A D 0 4 2 245 0 01</b>					G. State Facility's ID <b>CA ADD 4 22 45 901</b>
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	L. Waste No.		
a. Waste Naptha UN 2553 Combustible Liquid	0 0	DM	140	G	State EPA/Other		
b. Waste Corrosive Liquid NOS NA 9193 (Oxidyzer) Corrosive Liquid	0 01	DM	30	G	State EPA/Other		
c. Hazardous waste Liquid NOS NA 9189 (Brite Dip)	0 01	DM	30	G	State EPA/Other		
d.					State EPA/Other		
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above					
		a. 01	b. 01				
		c. 01	d.				
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.							
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.							
Printed/Typed Name <b>STEVEN PENNINGTON</b>		Signature <i>Steven Pennington</i>		Month Day Year <b>10 4 21 7818</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature <i>Javier Hernandez</i>		Month Day Year <b>09 8 27 88</b>			
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name		Signature		Month Day Year			
19. Discrepancy Indication Space							
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.							
Printed/Typed Name <b>FRANK FORD</b>		Signature <i>Frank Ford</i>		Month Day Year <b>10 4 21 7818</b>			

State of California—Health and Welfare Agency Form Approved OMB No. 2050-0039 (Expires 9-30-88) Please print or type. (Form designed for use on elite (12-pitch typewriter).		9/12/88	SHIPPER# 20119	87119175
<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No.	Manifest Document No.	
3. Generator's Name and Mailing Address		GAD 981 396 971		
SERRACIN MAGNEDYNE 2258 RUTHERFORD ROAD, CARLSBAD, CA., 92008				
4. Generator's Phone ( 619 438-3321)				
5. Transporter 1 Company Name		6. US EPA ID Number		
OMEGA RECOVERY SERVICES		I CAD 042245001		
7. Transporter 2 Company Name		8. US EPA ID Number		
OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD. WHITTIER, CA. 90602		I CAD 042 245 001		
9. Designated Facility Name and Site Address		10. US EPA ID Number		
OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD. WHITTIER, CA. 90602		I CAD 042 245 001		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers	13. Total Quantity	
a. HAZARDOUS WASTE LIQUID NOS NA 9189		No. Type		
b. FLAMMABLE WASTE LIQUID N.O.S un 1993		00 3 D M 010111615		
c. FLAMMABLE LIQUID FLAMMABLE WASTE LIQUID N.O.S. UN 1993		010 3 D M 010111615		
d. FLAMMABLE LIQUID FLAMMABLE WASTE LIQUID N.O.S UN 1993		010 11 D M 0101015		
J. Additional Descriptions for Materials Listed Above		010 11 D M 0101015		
K. Handling Criteria for Materials				
15. Special Handling Instructions and Additional Information				
a) FLUROSOLVE TF      d) MEIHYLENE CHLORIDE				
b) NAPHTHA      c) ACETONE				
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.				
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.				
Printed/Typed Name		Signature		
X John Miller		John Miller		
		Month Day Year	10/12/88	
17. Transporter 1 Acknowledgement of Receipt of Materials				
Printed/Typed Name		Signature		
JAVIER HERNANDEZ		Javier Hernandez		
		Month Day Year	09/15/88	
18. Transporter 2 Acknowledgement of Receipt of Materials				
Printed/Typed Name		Signature		
		Month Day Year	09/15/88	
19. Discrepancy Indication Space				
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.				
Printed/Typed Name		Signature		
FRANK FORD		Frank Ford		
		Month Day Year	10/9/22/88	

While TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS  
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

11/28/88 SHIPPER #18747

Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

**UNIFORM HAZARDOUS  
WASTE MANIFEST**

1 Generator's US EPA ID No.

CAD 981 396 971

Manifest  
Document No.

2. Page 1  
of 1

Information in the shaded areas  
is not required by Federal law.

3. Generator's Name and Mailing Address

SERRACIN MAGNEDYNE  
2258 RUTHERFORD ROAD, CARLSBAD, CA 92008

4. Generator's Phone 619 438-3321

5. Transporter 1 Company Name

OMEGA RECOVERY SERVICES

7. Transporter 2 Company Name

OMEGA RECOVERY SERVICES  
12504 E. WHITTIER BLVD.  
WHITTIER, CA 90602

9. Designated Facility Name and Site Address

OMEGA RECOVERY SERVICES

12504 E. WHITTIER BLVD.

WHITTIER, CA 90602

6. US EPA ID Number

CAD 042 245 001

8. US EPA ID Number

CAD 042 245 001

10. US EPA ID Number

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

a. HAZARDOUS WASTE LIQUID NOS NA 9189 N.O.S

12. Containers  
No. Type

13. Total  
Quantity

14. Unit  
Wt/Vol

15. Waste No.

01013 DIM 1 1415 G State

EPA/Other

b. FLAMMABLE WASTE LIQUID N.O.S UN 1993

0,0,1 DIM 1 40 G State

EPA/Other

c. FLAMMABLE WASTE LIQUID N.O.S UN 1993

01012 DIM 1 70 G State

EPA/Other

d. FLAMMABLE WASTE LIQUID N.O.S UN 1993

01012 DIM 1 70 G State

EPA/Other

FLAMMABLE LIQUID

J. Additional Descriptions for Materials Listed Above

K. Handling Codes for Wastes Listed Above

a. 01 b. 01

c. 01 d. 01

15. Special Handling Instructions and Additional Information

A) FLUROSOLVE TF

D) METHYLENE CHLORIDE

B) NAPHTHA

C) ACETONE

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment. OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

JOHN MILLER

Signature

Jane E. Miller

Month Day Year

11/24/88

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

JAVIER HERNANDEZ

Signature

Jan Hernandez

Month Day Year

11/20/88

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

FRANK FORD

Signature

Frank Ford

Month Day Year

11/20/88

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name

FRANK FORD

Signature

Frank Ford

Month Day Year

11/24/88

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

TRANSPORTER

FACILITY

DHS 8022 A (1/87)

EPA 8700—22

(Rev. 9-86) Previous editions are obsolete.





White TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS



To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

Please print or type (Form designed for use on elite (12-pitch typewriter).

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 396 971</b>	Manifest Document No. <b>4-1-2-1</b>	2 Page 1 of <b>1</b>	Information in the shaded areas is not required by Federal law		
3. Generator's Name and Mailing Address <b>SIERRACIN MAGNEDYNE 2258 RUTHERFORD ROAD, CARLSBAD, CA. 92008</b>		A. State Manifest Document Number <b>88345415</b>					
4. Generator's Phone (619) 438-3321		B. State Generator's ID					
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	C. State Transporter's ID <b>208451</b>				
7. Transporter 2 Company Name		B. US EPA ID Number	D. Transporter's Phone <b>213/698-0991</b>				
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD. WHITTIER, CA. 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID				
			F. Transporter's Phone				
			G. State Facility's ID <b>CAD 041 145 145 441</b>				
			H. Facility's Phone <b>213/698-0991</b>				
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) <b>HAZARDOUS WASTE LIQUID N.O.S., ORM-E MAXXX (FREON)</b>		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.		
					State <b>211</b>		
					EPA/Other <b>F001</b>		
13. WASTE PETROLEUM OIL N.O.S., COMBUSTIBLE LIQUID NA 1270					State <b>221</b>		
					EPA/Other <b>D001</b>		
14. WASTE NAPHTHA, COMBUSTIBLE LIQUID , UN2553					State <b>213</b>		
					EPA/Other <b>D001 Low Ign.</b>		
15. WASTE FLAMMABLE LIQUID N.O.S., UN 1993 (Coolant)					State <b>214</b>		
					EPA/Other <b>D001</b>		
J. Additional Descriptions for Materials Listed Above a.b.c.d.-Material for disposal		K. Handling Codes for Wastes Listed Above					
		a.	b.				
		c.	d.				
		<b>01</b>	<b>01</b>				
		<b>01</b>	<b>01</b>				
16. Special Handling Instructions and Additional Information Profile#B10295 B10299 B10298 F***295		*Emergency#619/438-3321					
GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.							
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.							
T R A N S P O R T E R		Printed/Typed Name <b>J B LEGRAND</b>	Signature 	Month <b>11</b>	Day <b>12</b>	Year <b>0291</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name <b>JAVIER HERNANDEZ</b>	Signature 	Month <b>11</b>	Day <b>12</b>	Year <b>0291</b>	
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name	Signature	Month	Day	Year	
F A C I L I T Y		19. Discrepancy Indication Space					
		20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.	Printed/Typed Name <b>JULIA H. HILL</b>	Signature 	Month <b>11</b>	Day <b>12</b>	Year <b>0291</b>

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 396 971</b>	Manifest Document No. <b>41511118</b>	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>SIERRACIN MAGNEDYNE 2258 RUTHERFORD ROAD, CARLSBAD, CA. 92008</b>		A. State Manifest Document Number <b>88345418</b>				
4. Generator's Phone <b>(619) 438-3321</b>		B. State Generator's ID				
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	C. State Transporter's ID <b>308451</b>			
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213/698-0991</b>			
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD. WHITTIER, CA. 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID			
			F. Transporter's Phone			
			G. State Facility's ID <b>CAD 042 245 001</b>			
			H. Facility's Phone <b>213/698-0991</b>			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)  a. <b>WASTE OXIDIZER, CORROSIVE LIQUID N.O.S. NA 9193</b>		12. Containers No. <b>003</b>	13. Total Quantity Type <b>D M</b>	14. Unit Wt/Vol <b>001/40 G</b>	I. Waste No. <b>State 123 EPA/Other D001</b>	
b.					State	
c.					EPA/Other	
d.					State	
					EPA/Other	
J. Additional Descriptions for Materials Listed Above <b>XXXXXXXXXXXXXX</b> a.-Material for disposal		K. Handling Codes for Wastes Listed Above a. <b>D</b> b.				
		c. <b>D</b> d.				
15. Special Handling Instructions and Additional Information <b>Profile#B11787</b>						
*Emergency# <b>619/438-3321</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>J.B. LEGRANT</b>		Signature 		Month <b>12</b>	Day <b>29</b>	Year <b>1991</b>
TRANSPORTER		17. Transporter 1 Acknowledgement of Receipt of Materials				
Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature 		Month <b>11</b>	Day <b>11</b>	Year <b>1991</b>
FACILITY		18. Transporter 2 Acknowledgement of Receipt of Materials				
Printed/Typed Name		Signature 		Month <b>11</b>	Day <b>11</b>	Year <b>1991</b>
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19						
Printed/Typed Name <b>J. B. Legrant</b>		Signature 		Month <b>11</b>	Day <b>11</b>	Year <b>1991</b>

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>C A D 9 813 96 971</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>SIERRACIN MAGNEDYNE</b> 2258 Rutherford, Carlsbad, CA 92008				A. State Manifest Document Number <b>88614947</b>		
4. Generator's Phone ( 619 438-3321				B. State Generator's ID		
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>C A D 0 4 2 2 4 5 0 0 1</b>			C. State Transporter's ID <b>075455</b>	
7. Transporter 2 Company Name		8. US EPA ID Number			D. Transporter's Phone (213) 698-0891	
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES</b> 12504 E. Whittier Blvd. Whittier, CA 90602		10. US EPA ID Number <b>C A D 0 4 2 2 4 5 0 0 1</b>			E. State Transporter's ID	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity Wt/Vol	14. Unit Wt/Vol	F. Transporter's Phone	
a. Waste Petroleum oil, N.O.S. NA 1270 (water soluble oil) Combustible		518 01/18	DM 1	G	G. State Facility's ID <b>CAD042245001</b>	
b. Waste Dichloromethane ORM-A UN 1593 (Methylene Chloride)		006 002	DM 1	G	H. Facility's Phone (213) 698-0891	
c. Waste Acetone UN 1090 Flammable liquid		904	DM 01011715	G	I. Waste No.	
d. Waste Petroleum Naptha UN 2553 Flammable liquid		001 001	DM 000050	G	J. Handling Codes for Wastes Listed Above	
J. Additional Descriptions for Materials Listed Above		a. 01	b. 01	c. 01	d. 01	
15. Special Handling Instructions and Additional Information		Profile No.' All1980, 11981, 11983, 11984, 11985, 11986, 11987.				
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.		It I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, If I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.				
Printed/Typed Name <b>JBLEGRAND</b>		Signature 		Month Day Year	1/02/81	
TRANSPORTER		17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature 	Month Day Year	1/02/81
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature				
FACILITY		19. Discrepancy Indication Space				
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>Frank Ford</b>		Signature 	Month Day Year	1/02/81		

Do Not Write Below This Line

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>C AD 9 81 3 96 9 71</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>Sierracin Magnedyne</b> <b>2258 Rutherford, Carlsbad, CA 92008</b>		A. State Manifest Document Number <b>88675895</b>				
4. Generator's Phone ( <b>619 438-3321</b> )		B. State Generator's ID <b>012455</b>				
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	C. State Transporter's ID <b>213/698-0991</b>			
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213/698-0991</b>			
9. Designated Facility Name and Site Address <b>Omega Recovery Services</b> <b>12504 E. Whittier Blvd.</b>		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID <b>012455</b>			
Whittier, CA 90608			F. Transporter's Phone <b>213/698-0991</b>			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. <b>001</b>	Type <b>DM</b>	13. Total Quantity <b>010010</b>	14. Unit Wt/Vol <b>G</b>	15. Waste No. <b>State</b>
Waste Petroleum oil, N.O.S. NA 1270 (waste oil) Flammable liquid						EPA/Other
b Hazardous waste liquid N.O.S. NA 9189 (Freon TF) ORM-E		<b>002</b> <b>004</b>	DM	<b>001/100</b>	G	State
c Hazardous waste solid N.O.S. NA 9189 (Empty drums) ORM-E		<b>015</b> <b>022</b>	DM	<b>00100</b>	P	EPA/Other
d Flammable waste Liquid UN 1993 (Varnish) Flammable liquid		<b>003</b> <b>008</b>	DM	<b>010650</b>	G	State
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
		a. <b>01</b>	b. <b>01</b>			
		c. <b>01</b>	d. <b>01</b>			
15. Special Handling Instructions and Additional Information B) Material to be recycled back to customer. C) Empty drums to be disposed. Profile No.'s A11980, 11981, 11983, 11984, 11985, 11986, 11987.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, If I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>J. B. LEGRAND</b>		Signature 		Month Day Year <b>25 OCT 89</b>		
TRANSPORTER		17. Transporter 1 Acknowledgement of Receipt of Materials		Month Day Year <b>10 24 89</b>		
Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature 		Month Day Year <b>10 25 89</b>		
FACILITY		18. Transporter 2 Acknowledgement of Receipt of Materials		Month Day Year <b>11 11 89</b>		
Printed/Typed Name		Signature				
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name <b>FRANK FORD</b>		Signature 		Month Day Year <b>11 12 89</b>		

Do Not Write Below This Line

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>C AD 9 813 96 9 71</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>Sierracin Magnedyne 2258 Rutherford, Carlsbad, CA 92008</b>		A. State Manifest Document Number <b>88675896</b>				
4. Generator's Phone <b>619) 438-3321</b>		B. State Generator's ID				
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>ICAD 0421245 001</b>	C. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone			
9. Designated Facility Name and Site Address <b>Omega Recovery Services 12504 E. Whittier Blvd. Whittier, CA 90602</b>		10. US EPA ID Number <b>ICAD 0421245 001</b>	E. State Transporter's ID			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. & Type 001 DM	13. Total Quantity <b>000100</b>	14. Unit Wt/Vol <b>P</b>	L. Waste No. State	
a. <del>Hazardous waste. Section N.O.S. ORME</del> <del>N-209</del> (Lead-Paste) See <del>list attached</del>					EPA/Other	
b. <del>Waste Petroleum oil N.O.S.</del> NA <del>4970</del> (Gelling oil) Flammable liquid		002 DM	000100	T	EPA/Other	
c. <del>Waste Oxidizer Liquid N.O.S.</del> NA 9193 (Bright Dip) Corrosive		003 DM	001060	G	EPA/Other	
d. <del>Waste Oxidizer Liquid N.O.S.</del> NA 9193 Corrosive		001 DM	000050	G	EPA/Other	
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes a. 01 b. 01 c. 01 d. 0				
L. Special Handling Instructions and Additional Information A) LAB PACK. SEE ATTACHED LIST. Profile No.'s A11980, 11981, 11983, 11984, 11985, 11986						
M. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>JBLEGRAND</b>		Signature 		Month Day Year <b>1/24/89</b>		
N. TRANSPORTER 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature 		Month Day Year <b>1/24/89</b>		
O. TRANSPORTER 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month Day Year		
P. FACILITY Discrepancy Indication Space						
Q. FACILITY Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name <b>FRANK FORD</b>		Signature 		Month Day Year <b>1/24/89</b>		

State of California—Health and Welfare Agency  
Form Approved OMB No. 2050—0039 (Expires 9-30-91)  
Please print or type. (Form designed for use on elite 612-pitch typewriter).

See Instructions on Back of Page 6  
and Front of Page 7

Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 396 971</b>	Manifest Document No.	2. Page 1 of Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address <b>SERRACIN MAGNEDYNE 2258 RUE ERFORD RD.. CARLSBAD, CA 92008</b>		A. State Manifest Document Number <b>88675944</b>		
4. Generator's Phone ( <b>619 438-3321 X 245</b> )		B. State Generator's ID		
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		8. US EPA ID Number <b>CAD 042 245001</b>	C. State Transporter's ID <b>042 450</b>	
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213/698-0991</b>	
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD WHITTIER, CA 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol
a. WASTE LAB PAKS HAZWASTE SOLID N.O.S ORM-E NA-9089		004 005 DM	001800	P EPA/Other <b>D002</b>
b. WASTE FLAMMABLE LIQUID XXXXXXX XXAXXX (VARNISH) UN 1993		008 CN	000140	E EPA/Other <b>D001</b>
c. FLAMMABLE WASTE LIQUID ( MIX SOLVENT ) UN 1993		002 Cn	11110	E EPA/Other <b>F005</b>
d. HAZ WASTE SOLID (ADHESIVE) ORM-E NA 9189		003 Cn	11115	G EPA/Other <b>G002</b>
14. Additional Descriptions for Materials Listed Above		K. Handling Codes for Waste Listed Above		
		a. 01	b. 01	
		c. 01	d. 01	-
15. Special Handling Instructions and Additional Information PROFILE NUMBERS A-11980, A11986 <b>XXXXXX</b> A-12034- AB PAKS A-11986- VARNI H A-11980- MIX SOLVENT A-12035- ADHESIVE				
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above in proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.				
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.				
Printed/Typed Name <b>ARTHUR T BORN JR</b>		Signature <b>Arthur T Born Jr</b> Month Day Year <b>11/11/789</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials				
Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature <b>Javier Hernandez</b> Month Day Year <b>11/11/789</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials				
Printed/Typed Name		Signature		
19. Discrepancy Indication Space				
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.				
Printed/Typed Name <b>FRANK FOED</b>		Signature <b>Frank Foed</b> Month Day Year <b>11/11/89</b>		

Do Not Write Below This Line

DHS 8022 A (1/88)

EPA 8700-22

(Rev. 9-88) Previous editions are obsolete.

White: TSDF SEND THIS COPY TO DQHS WITHIN 30 DAYS

To: P.O. Box 3000, Sacramento, CA 9812

State of California—Health and Welfare Agency  
Form Approved OMB No. 2050—0039 (Expires 9-30-81)  
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6  
and Front of Page 7

Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 396 971</b>	Manifest Document No.	2. Page 1 of <b>Information in the shaded areas is not required by Federal law.</b>
3. Generator's Name and Mailing Address <b>SIERRACIN MAGNEDYNE</b> <b>2258 RUTHFORD RD., CARLSBAD, CA 92008</b>		A. State Manifest Document Number <b>88676998</b>		
4. Generator's Phone ( 619 438-3321		B. State Generator's ID <b>074455</b>		
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	C. State Transporter's ID <b>074455</b>	
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213 698-0991</b>	
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES</b> <b>12504 E. WHITTIER BLVD</b> <b>WHITTIER, CA 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID <b>074455</b>	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) <b>B. WASTE CORROSIVE LIQUID N.O.S NA 9193 (DEOXIDIZER)</b>		12. Containers No. <b>00055 G</b>	13. Total Quantity <b>00055 G</b>	14. Unit Wt/Vol <b>State 133</b>
b.				EPA/Other
c.				State
d.				EPA/Other
e.				State
f.				EPA/Other
g.				State
h.				EPA/Other
i.				State
j.				EPA/Other
k. Additional Descriptions for Materials Listed Above		K. Handling Codes for Waste Listed Above <b>a. 01 b. c. d.</b>		
15. Special Handling Instructions and Additional Information <b>PROFILE NUMBER A11987</b>				
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.				
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.				
Printed/Typed Name <b>Ronald Gaines</b>		Signature <b>Ronald Gaines 0522290</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature <b>Javier Hernandez 0522290</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		
19. Discrepancy Indication Space				
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.				
Printed/Typed Name <b>FRANK FORD</b>		Signature <b>Frank Ford 1052290</b>		

88676998  
IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7650

GENERATOR

TRANSPORTER

FACILITY

Do Not Write Below This Line

DHS 8022 A (1/88)

EPA 8700-22

(Rev. 9-88) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS

To: P.O. Box 3000, Sacramento, CA 95812

04/25/89 Shipper 20714

State of California—Health and Welfare Agency  
Form Approved OMB No. 2050—0039 (Expires 9-30-91)

Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6  
and Front of Page 7Department of Health Services  
Toxic Control Division  
Sacramento, California

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 396 971</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by law.	
3. Generator's Name and Mailing Address <b>Sierracin Magnedyne</b> 2248 Rutherford Rd., Carlsbad, CA 92008		A. State Manifest Document Number <b>88677327</b>				
4. Generator's Phone ( 619 438-3321, ext. 245		B. State Generator's ID				
5. Transporter 1 Company Name <b>Omega Recovery Services</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	C. State Transporter's ID			
7. Transporter 2 Company Name		B. US EPA ID Number	D. Transporter's Phone <b>213/698-0991</b>			
8. Designated Facility Name and Site Address <b>Omega Recovery Services</b> 12504 E. Whittier Blvd. Whittier, CA 90602		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID			
			F. Transporter's Phone			
			G. State Facility's ID <b>CAD0142245001</b>			
			H. Facility's Phone <b>213/698-0991</b>			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Qua	14. Unit Wt/Vol	L. Waste No.	
a. Flammable waste liquid NOS UN 1993 Flammable liquid		<b>003</b> <b>Q014</b>	DM	<b>0102300</b>	State G. EPA/Other	
b. Waste Ace one UN 1090 Flammable liquid		<b>003</b>	DM	<b>0101150</b>	State G. EPA/003	
c. Waste Corrosive liquid NOS NA 9193 Corrosive		<b>001</b>	DM	<b>11150</b>	State G. EPA/Other	
d. Hazardous waste liquid NOS NA 9189		<b>001</b>	DM	<b>150</b>	State G. EPA/Other	
J. Additional Descriptions for Materials Listed Above A) Na thia D) Brite Dip B) Acetone C) O idyzer		K. Handling Codes for Wastes Listed Above a. <b>01</b> b. <b>01</b> c. <b>01</b> d. <b>01</b>				
15. Special Handling Instructions and Additional Information All materials for disposal.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>John Miller</b>		Signature 		Month Day Year <b>05/08/89</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature 		Month Day Year <b>05/08/89</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name <b>Frank Ford</b>		Signature 		Month Day Year <b>05/08/89</b>		

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802. WITHIN CALIFORNIA CALL 1-800-882-7550



04/25/89 Shipper 20 14

State of California - Health and Welfare  
Form Approved GMB No. 2050-0039 (Expires 8-30-91)

Please print or type. (Form designed for use on elite (12-pitch typewriter))

See Instructions on Back of Page 6  
and Front of Page 7

Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CA D 981 3 96 9 71</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.			
G E N E R A T O R	3. Generator's Name and Mailing Address <b>Sierracin Magnedyne 2258 Rutherford Rd., Carlsbad, CA 92008</b>			A. State Manifest Document Number <b>88677328</b>				
	4. Generator's Phone ( 619 438-3321, ext. 245			B. State Generator's ID				
	5. Transporter 1 Company Name <b>Omega Recovery Services</b>			C. State Transporter's ID <b>CIA 042 245 001</b>				
	6. US EPA ID Number			D. Transporter's Phone <b>213/698-0991</b>				
	7. Transporter 2 Company Name			E. State Transporter's ID				
	8. US EPA ID Number			F. Transporter's Phone				
	9. Designated Facility Name and Site Address <b>Omega Recovery Services 12504 E. Whittier Blvd. Whittier, CA 90602</b>			G. Site Facility's ID <b>CIA D 042 245 001</b>				
	10. US EPA ID Number <b>CAD 042 245001</b>			H. Facility's Phone <b>213/698-0991</b>				
	11. US D & T Description (Including Proper Shipping Name, Hazard Class, and ID Number)				12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	L. Waste No.
	a. Waste Methylene Chloride ORM-A UN 1593				002	DM	<b>500/100</b>	State <b>211</b> EPA/Other <b>F001</b>
b. Hazardous waste Liquid NOS NA 9189 (Fluorosolv TF)				002	DM	<b>500/100</b>	State <b>211</b> EPA/Other	
c.							State EPA/Other	
d.							State EPA/Other	
J. Additional Descriptions for Materials Listed Above				K. Handling Codes for Wastes Listed Above				
				a.	b.			
				<b>01</b>	<b>01</b>			
				c.	d.			
15. Special Handling Instructions and Additional Information <b>Recycle both materials back to customer.</b>								
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.								
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, If I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.								
Printed/Typed Name <b>John Miller</b>		Signature 		Month Day Year <b>10 5 88 1819</b>				
17. Transporter 1 Acknowledgement of Receipt of Materials								
Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature 		Month Day Year <b>10 5 88 1819</b>				
18. Transporter 2 Acknowledgement of Receipt of Materials								
Printed/Typed Name		Signature		Month Day Year				
19. Discrepancy Indication Space								
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.								
Printed/Typed Name <b>FRANK FORD</b>		Signature 		Month Day Year <b>10 5 88 1819</b>				

Do Not Write Below This Line

White TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS

To: P.O. Box 3000, Sacramento, CA 5812

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No <b>CAD 981 396 971</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>STERRACT/MAGNEDYNE</b> 2258 RUTHFORD RD., CARL BAD, CA 92008		A. State Manifest Document Number <b>88681461</b>				
4. Generator's Phone <b>619 438 3321</b>		B. State Generator's ID				
5. Transporter Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	C. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213 698-0991</b>			
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES</b> 12504 E. WHITTIER BLVD. WHITTIER, CA 90602		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID			
11. USDOT Description (including Proper Shipping Name, Hazar Class, an ID number)		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.	
a. NAPHTHA WASTE, FLAMMABLE LIQUID UN 2553		2012 DM	00111/10	S-213	EPA/Other R005	
b. WASTE PETROLEUM OIL, N.O.S. FLAMMABLE LIQUID, N. 1270 (WASTE OIL)		01/10 DM	0105150	S-221	EPA/Other D001	
c. WASTE M.E.K, FLAMMABLE LIQUID, UN 1193		201 DM	0010150	S-212	EPA/Other F003	
d. WASTE ACETONE, FLAMMABLE LIQUID, UN 1090		2012 DM	10111/10	S-212	EPA/Other F003	
16. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
		a.	b.	c.	d.	
15. Special Handling Instructions and Additional Information <b>PROFILE NUMBER: B-10295, 10298, 0296, 10297</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economic & practicable and that I have selected the practicable method of treatment, storage, disposal currently available to me which minimizes the present and future threat to human health and the environment. OR, If I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>Ron Gaines</b>		Signature <b>Ron Gaines</b>		Month Day Year		
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>Robert CIRINCEY</b>		Signature <b>Tall</b>		Month Day Year		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name <b>John Hantz</b>		Signature <b>JH</b>		Month Day Year		

Please print or type. (Form designed to be used on elite (12-pitch typewriter).

See Instructions on Back of Page 6  
and Front of Page 7

Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 396 971</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>STER ACIN MAGNEDYNE</b> 2258 RUTHFORD RD ., CARLSBAD, CA 92008		A. State Manifest Document Number <b>88681463</b>				
4. Generator's Phone (619) 438-3321		B. State Generator's ID				
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	C. State Transporter's ID <b>110237</b>			
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213 698-0991</b>			
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES</b> 12504 E. WHITTIER BLVD WHITTIER, CA 90602		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) a. HAZARDOUS WASTE LIQUID, NOS, ORM-E NA 9189 (FREON TF)		12. Containers No. <b>CAD 2 DM</b>	13. Total Quantity <b>0101/110</b>	14. Unit Wt/Vol	15. Waste No. <b>211</b>	
b.					EPA/Other <b>D001</b>	
c.					State	
d.					EPA/Other	
J. Additional Descriptions for Materials Listed Above A) FOR RECYCLE		K. Handling Codes for Wastes Listed Above a. <b>1</b> b.				
16. Special Handling Instructions and Additional Information PROFILE NUMBER B 10298		c. <b>1</b> d.				
17. Generator's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>Ron Gaines</b>		Signature 		Month Day Year <b>11/11/1989</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>KOBERT CIRINGANO</b>		Signature 		Month Day Year <b>11/11/1990</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>John HALTE</b>		Signature 		Month Day Year <b>11/12/1990</b>		

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CADI 1981 396 971</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>SIERRACIN MAGNEDYNE 2258 RUTHERFORD RD., CARLSBAD, CA 92008</b>		A. State Manifest Document Number <b>88683413</b>				
4. Generator's Phone <b>819-438-3321</b>		B. State Generator's ID				
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	C. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone			
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD WHITTIER, CA 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID			
			F. Transporter's Phone			
			G. State Facility's ID			
			H. Facility's Phone			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.	
a. WASTE DICHLOROMETHANE ORM-A UN 1593 (METHYLENE CHLORIDE WASTE)		0102	DM	0010165 G	211 EPA/Other F002	
b. WASTE [REDACTED] (METHYLENE CHLORIDE WASTE) (PHOTO CLEANER) EMPTY DRUMS		010	DM	0010100 P	214 EPA/Other F005	
c. WASTE PETROLEUM OIL FLAMMABLE LIQUID N.O.S (WATER SOLUBLE OIL) NA 1270		016	DM	0010100 G	221 EPA/Other D001	
d. HAZARDOUS WASTE SOLID N.O.S ORM-E (LAB PACK) NA 9189		0102	DM	0010100 P	551 EPA/Other D001	
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
		a.	b.	01 01		
		c.	d.	01 01		
15. Special Handling Instructions and Additional Information <b>PROFILE NUMBERS A-11987, 11980, 12035, 11982, 11984, 12034, 16139, 16138</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>ARTHUR J FORD JR</b>		Signature <b>Arthur J Ford Jr</b> Month Day Year <b>10/40/90</b>				
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature <b>Javier Hernandez</b> Month Day Year <b>08/03/90</b>				
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature				
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name <b>FRANK FORD</b>		Signature <b>Frank Ford</b> Month Day Year <b>10/40/90</b>				

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 1396 971</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>SIERRACIN MAGNEDYNE 2258 RUTHERFORD RD., CARLSBAD, CA 92008</b>		A. State Manifest Document Number <b>88683538</b>				
4. Generator's Phone <b>619 438-3321</b>		B. State Generator's ID				
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	C. State Transporter's ID <b>012455</b>			
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213 698-0991</b>			
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD WHITTIER, CA 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID			
			F. Transporter's Phone			
			G. State Facility's ID <b>CAD 042 2245091</b>			
			H. Facility's Phone <b>213 698-0991</b>			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	1. Waste No.	
a. <b>NOS (MOULDING COMPOUND)</b> N.O.S		<b>DM</b>			State <b>133</b> EPA/Other <b>D002</b>	
b. WASTE FLAMMABLE LIQUID (WASTE <b>NAPTHA</b> ) UN 1090		<b>0011</b>	<b>DN</b>	<b>000050 G</b>	State <b>212</b> EPA/Other <b>F003</b>	
c. WASTE ADHESIVE FLAMMABLE UN 1133 (CYCLEWELD ADHESIVE)		<b>0012</b>	<b>PL</b>	<b>0001315 G</b>	State <b>351</b> EPA/Other <b>D001</b>	
d. HAZARDOUS WASTE SOLID N.O.S ORM-E (MOULDING COMPOUND) NA 9189		<b>0017</b>	<b>PL</b>	<b>00035 G</b>	State <b>491</b> EPA/Other <b>D001</b>	
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
		a.	b.			
		c.	d.			
15. Special Handling Instructions and Additional Information <b>PROFILE NUMBERS A11987, 11980, 12035, 11982</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name		Signature				Month Day Year
						<b>05/11/90</b>
TRANSPORTER		17. Transporter 1 Acknowledgement of Receipt of Materials				
		Printed/Typed Name <b>JAVIER HERNANDEZ</b>				Signature <b>Javier Hernandez</b>
						Month Day Year <b>105/11/90</b>
FACILITY		18. Transporter 2 Acknowledgement of Receipt of Materials				
		Printed/Typed Name				Signature
						Month Day Year
		19. Discrepancy Indication Space				
FACILITY		20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.				
		Printed/Typed Name <b>FRANK FORD</b>				Signature <b>Frank Ford</b>
						Month Day Year <b>105/11/90</b>

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8902; WITHIN CALIFORNIA CALL 1-800-852-7550

TRANSPORTER

FACILITY

Do Not Write Below This Line

State of California—Health and Welfare Agency  
Form Approved OMB No. 2050—0039 (Expires 9-30-81)  
Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6  
and Front of Page 7

Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 896 971</b>	Manifest Document No.	2. Page 1 of <b>1</b>	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>SIERRACIN MAGNEDYNE 2258 RUTHERFORD RD., CARLSBAD, CA 92008</b>		A. State Manifest Document Number <b>88683539</b>				
4. Generator's Phone ( <b>619 438-3321</b> )		B. State Generator's ID				
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 1245 001</b>	C. State Transporter's ID <b>012455</b>			
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213 698-0991</b>			
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD WHITTIER, CA 90602</b>		10. US EPA ID Number <b>CAD 042 1245 001</b>	E. State Transporter's ID			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. <b>1</b>	Type <b>DM</b>	13. Total Quantity <b>1</b>	14. Unit Wt/Vol <b>512</b>	L Waste No. <b>512</b>
b. HAZARDOUS WASTE SOLID ORM-E NA 9189 (EMPTY OPEN TOP DRUM)						EPA/Other <b>D001</b>
c. HAZARDOUS WASTE SOLID ORM-E NA 9189 (EMPTY CLOSED TOP DRUMS)		<b>0104</b>	<b>DM</b>	<b>0.01160</b>	<b>P</b>	State <b>512</b> EPA/Other <b>D001</b>
c. HAZARDOUS WASTE LIQUID ORM-E NA 9189 (WASTE FREON)						State EPA/Other
d. HAZARDOUS WASTE LIQUID ORM-E NA 9189 (WATER - OIL) WASTE						State EPA/Other
J. Additional Descriptions for Materials Listed Above <b>B. ARE EMPTY DRUMS</b>		K. Handling Codes for Wastes Listed Above <b>a. b. c. d.</b>				<b>0/ 0/ 0/ 0/</b>
16. Special Handling Instructions and Additional Information <b>PROFILE NUMBERS A11987, 11980, 12035, 11982</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>Ronald Gaines</b>		Signature 		Month Day Year <b>05/11/90</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature 		Month Day Year <b>05/11/90</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>FRANK FORD</b>		Signature 		Month Day Year <b>05/11/90</b>		

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

TRANSPORTER

FACILITY

Do Not Write Below This Line

DHS 8022 A (1/88)

EPA 8700—22

(Rev. 9-88) Previous editions are obsolete.

While TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS

To: P.O. Box 3800, Sacramento, CA 95812

**Revised Manifest Summary Report**

**SIERRACIN MAGNEDYNE**

**Sierracin Corporation**

Manifest Date	Bates#	Manifest#	Quantity	Units	Gallons	Code	# Trips	Assessed (gl) Volume	
		88345415		6797.1	LBS		CMP		
		88345418		1167.6	LBS		CMP		
04/27/1988		87118723		3419.4	LBS		CMP		
04/27/1988		87118737		1668	LBS		CMP		
09/22/1988		87119175		3669.6	LBS		CMP		
12/02/1988		87119444		2877.3	LBS		CMP		
05/08/1989		88677327		3753	LBS		CMP		
05/08/1989		88677328		1668	LBS		CMP		
10/24/1989		88614947		10008	LBS		CMP		
10/24/1989		88675895		7172	LBS		CMP		
10/24/1989		88675896		834	LBS		CMP		
11/17/1989		88675944		1342.1	LBS		CMP		
04/03/1990		88683413		11297.1	LBS		CMP		
05/11/1990		88683538		1000.8	LBS		CMP		
05/11/1990		88683539		1911.4	LBS		CMP		
05/22/1990		88676998		458.7	LBS		CMP		
11/19/1990		88681461		6880.5	LBS		CMP		
11/19/1990		88681463		917.4	LBS		CMP		

Total Records: 18

Default Volume: 0

Total Waste Volume: 33.421

### Revised Manifest Summary Report

**SIERRACIN TRANSFLEX**

**Sierracin Corporation**

Manifest Date	Bates#	Manifest#	Quantity	Units	Gallons	Code	# Trips	Assessed (gl) Volume	
09/16/1987		87113406		2293.5	LBS		CMP		
01/31/1988		87113415		1251	LBS		CMP		
04/06/1988		87113418		1251	LBS		CMP		
07/01/1988		87113498		1251	LBS		CMP		

Total Records: 4

Default Volume: 0

Total Waste Volume: 3.0233

lc_group_name	Sierracin Corporation
grp_calc_volume:	36.4443 tons
generator_name	SIERRACIN MAGNEDYNE
lc_name:	Sierracin Corporation
manifest_number	manifest_quantity_ton
87118723	1.7097 tons
87118737	0.834 tons
87119175	1.8348 tons
87119444	1.43865 tons
88345415	3.39855 tons
88345418	0.5838 tons
88614947	5.004 tons
88675895	3.586 tons
88675896	0.417 tons
88675944	0.67105 tons
88676998	0.22935 tons
88677327	1.8765 tons
88677328	0.834 tons
88681461	3.44025 tons
88681463	0.4587 tons
88683413	5.64855 tons
88683538	0.5004 tons
88683539	0.9557 tons
generator_name	SIERRACIN TRANSFLEX
lc_name:	Sierracin Corporation
manifest_number	manifest_quantity_ton
87113406	1.14675 tons
87113415	0.6255 tons
87113418	0.6255 tons

---

87113498

0.6255 tons

lc_group_name	Sierracin Corporation
grp_calc_volume:	36.4443 tons
generator_name	SIERRACIN MAGNEDYNE
lc_name:	Sierracin Corporation
manifest_number	manifest_quantity_ton
87118723	1.7097 tons
87118737	0.834 tons
87119175	1.8348 tons
87119444	1.43865 tons
88345415	3.39855 tons
88345418	0.5838 tons
88614947	5.004 tons
88675895	3.586 tons
88675896	0.417 tons
88675944	0.67105 tons
88676998	0.22935 tons
88677327	1.8765 tons
88677328	0.834 tons
88681461	3.44025 tons
88681463	0.4587 tons
88683413	5.64855 tons
88683538	0.5004 tons
88683539	0.9557 tons
generator_name	SIERRACIN TRANSFLEX
lc_name:	Sierracin Corporation
manifest_number	manifest_quantity_ton
87113406	1.14675 tons
87113415	0.6255 tons
87113418	0.6255 tons

---

87113498

0.6255 tons



lc_group_name	Sierracin Corporation
grp_calc_volume:	36.4443 tons
generator_name	SIERRACIN MAGNEDYNE
lc_name:	Sierracin Corporation
manifest_number	manifest_quantity_ton
87118723	1.7097 tons
87118737	0.834 tons
87119175	1.8348 tons
87119444	1.43865 tons
88345415	3.39855 tons
88345418	0.5838 tons
88614947	5.004 tons
88675895	3.586 tons
88675896	0.417 tons
88675944	0.67105 tons
88676998	0.22935 tons
88677327	1.8765 tons
88677328	0.834 tons
88681461	3.44025 tons
88681463	0.4587 tons
88683413	5.64855 tons
88683538	0.5004 tons
88683539	0.9557 tons
generator_name	SIERRACIN TRANSFLEX
lc_name:	Sierracin Corporation
manifest_number	manifest_quantity_ton
87113406	1.14675 tons
87113415	0.6255 tons
87113418	0.6255 tons

---

87113498

0.6255 tons

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CA D 9 8 1 3 9 6 9 7 1</b>	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.		
3. Generator's Name and Mailing Address <b>Serracin Magnedyne 2258 Rutherford Road, Carlsbad, CA 92008</b>						A. State Manifest Document Number <b>87118737</b>	
4. Generator's Phone (619) 438-3321						B. State Generator's ID	
5. Transporter 1 Company Name <b>Omega Recovery Services</b>		6. US EPA ID Number <b>C A D 0 4 2 2 4 5 0 0 1</b>					C. State Transporter's ID
7. Transporter 2 Company Name		8. US EPA ID Number					D. Transporter's Phone <b>213/698-0991</b>
9. Designated Facility Name and Site Address <b>Omega Recovery Services 12512 E. Whittier Blvd. Whittier, CA 90602</b>		10. US EPA ID Number <b>C A D 0 4 2 2 4 5 0 0 1</b>					E. State Transporter's ID
							F. Transporter's Phone
							G. State Facility's ID <b>CADD142245001</b>
							H. Facility's Phone <b>213/698-0991</b>
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.		
G E N E R A T O R	a. Waste Naptha UN 2553 Combustible Liquid	3 0 0 1	DM	140	State EPA/Other		
	b. Waste Corrosive Liquid NOS NA 9193 (Oxidyzer) Corrosive Liquid	0 0 1	DM	30	State EPA/Other		
	c. Hazardous waste Liquid NOS NA 9189 (Brite Dip)	0 0 1	DM	30	State EPA/Other		
	d.					State EPA/Other	
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above					
		a. 01	b. 01				
		c. 01	d.				
15. Special Handling Instructions and Additional Information							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.							
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.							
Printed/Typed Name <b>STEVEN PENNINGTON</b>		Signature <i>Steven Pennington</i>		Month Day Year <b>10/4/27/88</b>			
TRANSPORTER		17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature <i>Javier Hernandez</i>		Month Day Year <b>09/27/88</b>			
FACILITY		18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name		Signature		Month Day Year			
19. Discrepancy Indication Space							
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.							
Printed/Typed Name <b>FRANK FORD</b>		Signature <i>Frank Ford</i>		Month Day Year <b>10/4/27/88</b>			

04/15/88

Shipper 15250

Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>C A D 98 13 9 6 97 1</b>	Manifest Document No.	2. Page 1 of 2	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>Serracin Magnedyne 2258 Rutherford Rd., Carlsbad, CA 92008</b>		A. State Manifest Document Number <b>87118723</b>				
4. Generator's Phone (619) 438-3321		B. State Generator ID				
5. Transporter 1 Company Name <b>Omega Recovery Services</b>		6. US EPA ID Number <b>C A D 04 2 24 5 001</b>	C. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213/698-0991</b>			
9. Designated Facility Name and Site Address <b>Omega Recovery Services 12512 E. Whittier Blvd. Whittier, CA 90602</b>		10. US EPA ID Number <b>C A D 04 2 245 001</b>	E. State Transporter's ID			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	L. Waste No.	
a. Hazardous Waste Liquid NOS NA 9189 (Fluorosolv TF)		0 0 5 DM	1210	6	261 EPA/Other	
b. Waste Methylene Chloride ORM-A UN 1593		0 0 2 DM	100	G	261 EPA/Other	
c. Waste Acetone UN 1090 Flammable Liquid		0 0 1 DM	50	G	State EPA/Other	
d. Waste Isopropyl Alcohol UN 1219 Flammable Liquid		0 0 1 DM	50	G	State EPA/Other	
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
		a. 01	G1			
		c. 01	01			
15. Special Handling Instructions and Additional Information						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>STEVEN PENNINGTON</b>		Signature <i>Steven Pennington</i>		Month Day Year <b>10/4/27/88</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name <b>JAVIER HERIVANDEZ</b>		Signature <i>Juan Hernandez</i>		Month Day Year <b>04/27/88</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name <b>FRANK FORD</b>		Signature <i>Frank Ford</i>		Month Day Year <b>10/4/27/88</b>		

9/12/88 SHIPPER# 20119

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

TRANSPORTER

FACILITY

DHS 8022 A (1/87)

EPA 8700-22

(Rev. 9-86) Previous editions are obsolete

White TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS  
To P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 396 971</b>	Manifest Document No.	2. Type of Waste	3. State Name
3. Generator's Name and Mailing Address <b>SERRACIN MAGNEDYNE 2258 RUTHERFORD ROAD, CARLSBAD, CA., 92008</b>				A. State Name	
4. Generator's Phone ( <b>619 438-3321</b> )				B. State Name	
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042245001</b>		C. State Name	
7. Transporter 2 Company Name		8. US EPA ID Number		D. State Name	
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD. WHITTIER, CA. 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>		E. State Name	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers	13. Total Quantity	14. Unit Weight	
a. HAZARDOUS WASTE LIQUID NOS NA 9189		No. <b>003</b>	D M <b>010111651G</b>		
b. FLAMMABLE WASTE LIQUID N.O.S un 1993 FLAMMABLE LIQUID		No. <b>0103</b>	D M <b>010111651G</b>		
c. FLAMMABLE WASTE LIQUID N.O.S. UN 1993 FLAMMABLE LIQUID		No. <b>01011</b>	D M <b>01010151G</b>		
d. FLAMMABLE WASTE LIQUID N.O.S UN 1993 FLAMMABLE LIQUID		No. <b>01011</b>	D M <b>01010151G</b>		
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Hazardous Materials			
		a. <b>01</b>	<b>01</b>	<b>01</b>	<b>01</b>
		b. <b>01</b>	<b>01</b>	<b>01</b>	<b>01</b>
15. Special Handling Instructions and Additional Information					
a) FLUROSOLVE TF      D) METHYLENE CHLORIDE					
B) NAPTHA					
C) ACETONE					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.					
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I can determine to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name <b>X John Miller</b>		Signature <b>John Miller</b>		Month <b>10</b>	Day <b>19</b>
17. Transporter 1 Acknowledgement of Receipt of Materials				Year <b>1988</b>	
Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature <b>Javier Hernandez</b>		Month <b>10</b>	Day <b>19</b>
18. Transporter 2 Acknowledgement of Receipt of Materials				Year <b>1988</b>	
Printed/Typed Name		Signature		Month	Day
19. Discrepancy Indication Space				Year	
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.					
Printed/Typed Name <b>FRANK FORD</b>		Signature <b>Frank Ford</b>		Month <b>10</b>	Day <b>19</b>
				Year <b>1988</b>	

State of California—Health and Welfare Agency  
Form Approved OM3 No. 2050—0038 (Expires 9-30-88)  
Please print or type. (Form designed for use on elite (12-pitch typewriter).

11/28/88 SHIPPER #18747

Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1 Generator's US EPA ID No. <b>CAD 981 396 971</b>	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address <b>SERRACIN MAGNEDYNE 2258 Rutherford Road, CARLSBAD, CA 92008</b>				A. State Manifest Document Number <b>87119444</b>	
4. Generator's Phone <b>(619) 438-3321</b>		6. US EPA ID Number <b>CAD 042 245 001</b>		B. State Generator's ID <b>904878</b>	
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		8. US EPA ID Number <b>CAD 042 245 001</b>		C. State Transporter's ID <b>213/698-0991</b>	
7. Transporter 2 Company Name				D. Transporter's Phone <b>213/698-0991</b>	
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD. WHITTIER, CA 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>		E. State Transporter's ID <b>213/698-0991</b>	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
a. HAZARDOUS WASTE LIQUID NOS NA 9189 N.O.S		01013 DIM	11415 G		State
b. FLAMMABLE WASTE LIQUID N.O.S UN 1993 FLAMMABLE LIQUID		0,0,1 DIM	1140 G		EPA/Other
c. FLAMMABLE WASTE LIQUID N.O.S UN 1993 FLAMMABLE LIQUID		01012 DIM	1170 G		State
d. FLAMMABLE WASTE LIQUID N.O.S UN 1993 FLAMMABLE LIQUID		01012 DIM	1170 G		EPA/Other
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above			
		a. 01	b. 01		
		c. 01	d. 01		
15. Special Handling Instructions and Additional Information					
A) FLUROSOLVE TF      D) METHYLENE CHLORIDE					
B) NAPHTHA      C) ACETONE					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.					
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment. OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name <b>JOHN MILLER</b>		Signature <i>John E. Miller</i>		Month Day Year <b>11/21/88</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature <i>Javier Hernandez</i>		Month Day Year <b>11/21/88</b>	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.					
Printed/Typed Name <b>FRANK FORD</b>		Signature <i>Frank Ford</i>		Month Day Year <b>11/29/88</b>	

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

GENERATOR

TRANSPORTER

FACILITY

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS  
To: P.O. Box 3000, Sacramento, CA 95812

INSTRUCTIONS ON THE BACK

04/25/89 Shipper 20714

State of California - Health and Welfare Agency  
Form Approved OMB No. 2050-0030 (Expires 9-30-91)

Please print or type. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6  
and Front of Page 7Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CA D 981 3 96 9 71</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address <b>Sierracin Magnedyne 2258 Rutherford Rd., Carlsbad, CA 92008</b>				A. State Manifest Document Number <b>88677328</b>	
4. Generator's Phone ( 619 ) 438-3321, ext. 245				B. State Generator's ID	
5. Transporter 1 Company Name <b>Omega Recovery Services</b>		6. US EPA ID Number <b>1 CAD 042 245 001</b>			C. State Transporter's ID <b>010384</b>
7. Transporter 2 Company Name		8. US EPA ID Number			D. Transporter's Phone <b>213/698-0991</b>
9. Designated Facility Name and Site Address <b>Omega Recovery Services 12504 E. Whittier Blvd. Whittier, CA 90602</b>		10. US EPA ID Number <b>CAD 042 245001</b>			E. State Facility's ID <b>CIAID1041212450101</b>
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	L Waste No.
a. Waste Methylene Chloride ORM-A UN 1593		902 DM	<b>0101/1010</b>	G	State 211 EPA/Other F001
b. Hazardous waste Liquid NOS (Fluorosolv TF) NA 9189		002 DM		G	State 211 EPA/Other
c.		1 1	<b>0101/100</b>		State EPA/Other
d.		1 1			State EPA/Other
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above			
		a. 01	b. 01		
		c.	d.		
15. Special Handling Instructions and Additional Information <b>Recycle both materials back to customer.</b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name <b>John Miller</b>		Signature <i>John Miller</i>		Month Day Year <b>10/08/89</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature <i>Javier Hernandez</i>		Month Day Year <b>10/08/89</b>	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.					
Printed/Typed Name <b>FRANK FORD</b>		Signature <i>Frank Ford</i>		Month Day Year <b>10/08/89</b>	

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-862-7650

TRANSPORTER

FACILITY

Do Not Write Below This Line

DHS 8022 A (1/88)

EPA 8700-22

(Rev. 9-88) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS

To: P.O. Box 3000, Sacramento, CA 95812

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

C 4/25/89

Shipper 20714




State of California—Health and Welfare Agency  
Form Approved OMB No. 2050-0039 (Expires 9-30-91)

Please print or type. (Form designed for use onelite (12-pitch typewriter).

See Instructions on Back of Page 6  
and Front of Page 7

Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 396 971</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
G E N E R A T O R	3. Generator's Name and Mailing Address <b>Sierracin Magnedyne 2258 Rutherford Rd., Carlsbad, CA 92008</b>		A. State Manifest Document Number <b>88677327</b>			
	4. Generator's Phone ( 619 438-3321, ext. 245		B. State Generator's ID			
T R A N S P O R T E R	5. Transporter 1 Company Name <b>Omega Recovery Services</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	C. State Transporter's ID		
	7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213/698-0991</b>		
F A C I L I T Y	9. Designated Facility Name and Site Address <b>Omega Recovery Services 12504 E. Whittier Blvd. Whittier, CA 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID		
				F. Transporter's Phone		
			G. State Facility's ID <b>CAD 042245001</b>			
			H. Facility's Phone <b>213/698-0991</b>			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	L. Waste No.	
a. Flammable waste liquid NOS UN 1993 Flammable liquid		003 9014	DM 1	0101200	G. State EPA/Other	
b. Waste Acetone UN 1090 Flammable liquid		003	DM 1	0101150	G. State EPA/Other	
c. Waste Corrosive liquid NOS NA 9193 Corrosive		001	DM 1	150	G. State EPA/Other	
d. Hazardous waste liquid NOS NA 9189		001	DM 1	50	G. State EPA/Other	
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
A) Naphtha D) Brite Dip		a. 01	b. 01			
B) Acetone		c. 01	d. 01			
C) Oxidizer						
16. Special Handling Instructions and Additional Information All materials for disposal.						
18. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, If I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>John Miller</b>		Signature <i>John Miller</i>		Month Day Year	<b>05/08/89</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature <i>Javier Hernandez</i>		Month Day Year	<b>05/08/89</b>	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>Frank Ford</b>		Signature <i>Frank Ford</i>		Month Day Year	<b>05/08/89</b>	

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>C A D 9 813 96 971</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>SIERRACIN MAGNEDYNE 2258 Rutherford, Carlsbad, CA 92008</b>		A. State Manifest Document Number <b>88614947</b>				
4. Generator's Phone ( 619 438-3321		B. State Generator's ID				
6. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>C A D 0 4 2 2 4 5 0 0 1</b>	C. State Transporter's ID <b>01245001</b>			
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>(213) 698-0991</b>			
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. Whittier Blvd. Whittier, CA 90602</b>		10. US EPA ID Number <b>C A D 0 4 2 2 4 5 0 0 1</b>	E. State Transporter's ID			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	L	Waste No.
a. Waste Petroleum oil, N.O.S. NA 1270 (water soluble oil) Combustible		<b>522 01/8</b>	DM 1	<b>009100</b>	G	State
b. Waste Dichloromethane ORM-A UN 1593 (Methylene Chloride)		<b>004 002</b>	DM 1	<b>010101715</b>	G	EPA/Other
c. Waste Acetone UN 1090 Flammable liquid		<b>004</b>	DM	<b>01011715</b>	G	State
d. Waste Petroleum Naptha UN 2553 Flammable liquid		<b>001 006</b>	DM	<b>000950</b>	G	EPA/Other
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
		a.	b.			
		c.	d.			
15. Special Handling Instructions and Additional Information						
Profile No.' All 1980, 11981, 11983, 11984, 11985, 11986, 11987.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>JBLEGRAND</b>		Signature 		Month Day Year <b>1/02/89</b>		
T R A N S P O R T E R 17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature 		Month Day Year <b>1/02/89</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month Day Year		
F A C I L I T Y 19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name <b>FRANKL FORED</b>		Signature 		Month Day Year <b>1/02/89</b>		

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; OR CALL 1-800-852-7550

FACILITY

Do Not Write Below This Line



IS 8022 A (1/88)

FA 8700-22

Rev. 9-88) Previous editions are obsolete.

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS

To: P.O. Box 3000, Sacramento, CA 95812

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 9 81 3 96 9 71</b>	Manifest Document No.	2. Page 1 of Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>Sierracin Magnedyne 2258 Rutherford, Carlsbad, CA 92008</b>		A. State Manifest Document Number <b>88675895</b>			
4. Generator's Phone ( 619 438-3321 )		B. State Generator's ID			
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	C. State Transporter's ID <b>072455</b>		
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213/698-0991</b>		
9. Designated Facility Name and Site Address <b>Omega Recovery Services 12504 E. Whittier Blvd. Whittier, CA 90600</b>		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID		
			F. Transporter's Phone		
			G. State Facility's ID <b>CADD0415124151011</b>		
			H. Facility's Phone <b>213/698-0991</b>		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	L. Waste No.
a. Waste Petroleum oil, N.O.S. NA 1270 (waste oil) Flammable liquid		001	DM	<b>01001010</b>	State
		1			EPA/Other
b. Hazardous waste liquid N.O.S. NA 9189 (Freon TF) ORM-E		002	DM	<b>0101/100</b>	State
		003			EPA/Other
c. Hazardous waste solid N.O.S. NA 9189 (Empty drums) ORM-E		015	DM	<b>0050100</b>	State
		016			EPA/Other
d. Flammable waste Liquid UN 1993 (Varnish) Flammable liquid		003	DM	<b>01016510</b>	State
		004			EPA/Other
J. Additional Descriptions for Materials Listed Above					
K. Handling Codes for Wastes Listed Above					
a. <b>01</b> b. <b>01</b>					
c. <b>01</b> d. <b>01</b>					
15. Special Handling Instructions and Additional Information B) Material to be recycled back to customer. C) Empty drums to be disposed. Profile No.'s A11980, 11981, 11983, 11984, 11985, 11986, 11987.					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.					
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name <b>J.B. LEGRAND</b>		Signature 		Month Day Year <b>210 24 89</b>	
TRANSPORTER		17. Transporter 1 Acknowledgement of Receipt of Materials		Month Day Year <b>10 24 89</b>	
		Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature 	
18. Transporter 2 Acknowledgement of Receipt of Materials				Month Day Year <b>10 24 89</b>	
FACILITY		Printed/Typed Name		Signature	
		19. Discrepancy Indication Space			
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.					
		Printed/Typed Name <b>FRANK FORD</b>		Signature 	
Month Day Year <b>110 24 89</b>					

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7650

GENERATOR

Do Not Write Below This Line

White TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS  
To P.O. Box 3000, Sacramento, CA 95812

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-862-7850

GENERATOR

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-862-7850

TRANSPORTER

FACILITY

DHS 8022 A (1/88)




EPA 8700-22

(Rev. 9-86) Previous editions are obsolete.

Do Not Write Below This Line

Where TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS

To: P.O. Box 3000, Sacramento, CA 95812

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>G AD 9 813 96 9 71</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>Sierracor Magnedyne</b> <b>2258 Rutherford, Carlsbad, CA 92008</b>				A. State Manifest Document Number <b>88675896</b>		
4. Generator's Phone <b>619) 438-3321</b>				B. State Generator's ID		
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>I CAD 042 1245 001</b>		C. State Transporter's ID <b>012455</b>		
7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone <b>213/698-0991</b>		
9. Designated Facility Name and Site Address <b>Omega Recovery Services</b> <b>12504 E. Whittier Blvd.</b> <b>Whittier, CA 90602</b>		10. US EPA ID Number <b>I CAD 042 1245 001</b>		E. State Facility's ID <b>CAD04124550101</b>		
				F. Facility's Phone <b>213/698-0991</b>		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	L Waste No.	
a. <del>Hazardous wastes Section N.O.S. ORME NOS</del> (Ink-Park) See list attached		001	DM	000000	State	
b. Waste Petroleum oil N.O.S. NA 9190 (Smoking oil) Flammable liquid		002	DM	000000	P EPA/Other	
c. Waste Oxidizer Liquid N.O.S. NA 9193 (Bright Dip) Corrosive		002	DM	001060	State	
d. Waste Oxidizer Liquid N.O.S. NA 9193 Corrosive		001	DM	000000	EPA/Other	
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
		a.	b.			
		c.	d.			
16. Special Handling Instructions and Additional Information						
A) LAB PACK. SEE ATTACHED LIST.						
Profile No.'s All1980, 11981, 11983, 11984, 11985, 11986						
18. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>JB LeGRAND</b>		Signature 		Month Day Year	1/24/89	
17. Transporter 1 Acknowledgement of Receipt of Materials				Month Day Year		
Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature 		Month Day Year	1/24/89	
18. Transporter 2 Acknowledgement of Receipt of Materials				Month Day Year		
Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name <b>FRANK FORD</b>		Signature 		Month Day Year	1/24/89	

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 396 971</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>SERRACIN MAGNEDYNE</b> 2258 RUTHERFORD RD., CARLSBAD, CA 92008		A. State Manifest Document Number <b>88675944</b>				
4. Generator's Phone ( <b>619 438-3321 X 245</b> )		B. State Generator's ID				
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245001</b>	C. State Transporter's ID			
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213/698-0991</b>			
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES</b> 12504 E. WHITTIER BLVD WHITTIER, CA 90602		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID			
			F. Transporter's Phone			
			G. State Facility's ID <b>CAD 0422245001</b>			
			H. Facility's Phone <b>213/698- XX 0991</b>			
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.	
a. WASTE LAB PAKS- HAZWASTE SOLID N.O.S ORM-E NA-9089		004 006	DM	01018190	P EPA/Other <b>D002</b>	
b. WASTE FLAMMABLE LIQUID <del>XXAEMXSM</del> <del>XXAEMXSM</del> (VARNISH) UN 1993		008	CN	000140	E EPA/Other <b>D001</b>	
c. FLAMMABLE WASTE LIQUID ( MIX SOLVENT) UN 1993		002	Cn	111110	E EPA/Other <b>F005</b>	
d. HAZ WASTE SOLID (ADHESIVE) ORM-E NA 9189		003	Cn	111115	G EPA/Other <b>D002</b>	
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
		a.	b.			
		c.	d.			
15. Special Handling Instructions and Additional Information PROFILE NUMBERS A-11980, A11986 <b>XXXXXX</b> A-12034- LAB PAKS A-11986- VARNISH A-11980- MIX SOLVENT A-12035- ADHESIVE						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>ARTHUR J FORN JR</b>		Signature <i>Arthur J Forn Jr</i>		Month Day Year <b>11/17/87</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature <i>Javier Hernandez</i>		Month Day Year <b>11/17/87</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year <b>11/17/87</b>		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>FRANK FORD</b>		Signature <i>Frank Ford</i>		Month Day Year <b>11/17/89</b>		

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7650

TRANSPORTER

FACILITY

Do Not Write Below This Line

While TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS  
To P.O. Box 3000, Sacramento, CA 95812

88683413  
WITHIN CALIFORNIA CALL 1-800-852-7560

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CADI 1981 396 0711</b>	Manifest Document No.	2. Page 1 of <b>Information in the shaded areas is not required by Federal law.</b>	
3. Generator's Name and Mailing Address <b>SIERRACIN MAGNEDYNE 2258 RUTHERFORD RD., CARLSBAD, CA 92008</b>		A. State Manifest Document Number <b>88683413</b>			
4. Generator's Phone <b>819-438-3321</b>		B. State Generator's ID			
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	C. State Transporter's ID <b>D05455</b>		
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213 698-0991</b>		
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD WHITTIER, CA 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID		
			F. Transporter's Phone		
			G. State Facility's ID <b>CADI01422451091</b>		
			H. Facility's Phone <b>213 698-0991</b>		
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. WASTE DICHLOROMETHANE ORM-A UN 1593 (METHYLENE CHLORIDEWASTE)		<b>0102 DM</b>	<b>0010015 G</b>		State <b>211</b> EPA/Other <b>F002</b>
b. <del>WASTE</del> <del>REMOVED FROM THIS LINE</del> (PHOTO CLEANER) <b>EMPTY DRUMS</b>		<b>0102 DM</b>	<b>0010010 P</b>		State <b>214</b> EPA/Other <b>F005</b>
c. WASTE PETROLEUM OIL FLAMMABLE LIQUID N.O.S (WATER SOLUBLE OIL) NA 1270		<b>0102 DM</b>	<b>0010010 G</b>		State <b>221</b> EPA/Other <b>D001</b>
d. HAZARDOUS WASTE SOLID N.O.S ORM-E (LAB PACK) NA 9189		<b>0102 DM</b>	<b>0010010 P</b>		State <b>551</b> EPA/Other <b>D001</b>
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above			
		a. <b>01</b>	b. <b>01</b>		
		c. <b>01</b>	d. <b>01</b>		
15. Special Handling Instructions and Additional Information <b>PROFILE NUMBERS A-11987,11980,12035,11982,11984,12034,16139,16138</b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable International and national government regulations.					
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name <b>ARTHUR J FORD JR</b>		Signature <i>Arthur J Ford Jr</i>		Month Day Year <b>10/03/90</b>	
TRANSPORTER 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature <i>Javier Hernandez</i>		Month Day Year <b>06/03/90</b>	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year	
FACILITY 19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>FRANK FORD</b>		Signature <i>Frank Ford</i>		Month Day Year <b>10/4/03/90</b>	

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 98L 396 971</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>SIERRACIN MAGNEDYNE 2258 RUTHERFORD RD., CARLSBAD, CA 92008</b>		A. State Manifest Document Number <b>88683538</b>				
4. Generator's Phone <b>819 438-3321</b>		B. State Generator's ID				
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	C. State Transporter's ID <b>012455</b>			
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213 698-0991</b>			
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD WHITTIER, CA 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID			
			F. Transporter's Phone			
			G. State Facility's ID <b>CAD 0412245001</b>			
			H. Facility's Phone <b>213 698-0991</b>			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. <b>1</b>	13. Total Quantity <b>DM</b>	14. Unit Wt/Vol <b>1</b>	I. Waste No. <b>State 133 EPA/Other D002</b>	
a. <b>N.O.S (WASTE )</b>						
b. <b>WASTE FLAMMABLE LIQUID (WASTE ) UN 1090 NAPTHA</b>		<b>001</b>	<b>DM</b>	<b>000050 G</b>	<b>State 212 EPA/Other F003</b>	
c. <b>WASTE ADHESIVE FLAMMABLE UN 1133 (CYCLEWELD ADHESIVE)</b>		<b>002</b>	<b>PL</b>	<b>000135 G</b>	<b>State 351 EPA/Other D001</b>	
d. <b>HAZARDOUS WASTE SOLID N.O.S ORM-E (MOULDING COMPOUND) NA 9189</b>		<b>003</b>	<b>PL</b>	<b>00035 G</b>	<b>State 491 EPA/Other D001</b>	
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
		a. <b>01</b>	b. <b>01</b>			
		c. <b>01</b>	d. <b>01</b>			
15. Special Handling Instructions and Additional Information <b>PROFILE NUMBERS A11987, 11980, 12035, 11982</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, If I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature		Month Day Year <b>05/11/90</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature		Month Day Year <b>05/11/90</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>FRANK FORD</b>		Signature		Month Day Year <b>05/11/90</b>		

Do Not Write Below This Line

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7560

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 896 971</b>	Manifest Document No.	2. Page 1 of Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address <b>SIERRACIN MAGNEDYNE 2258 RUTHERFORD RD., CARLSBAD, CA 92008</b>				A. State Manifest Document Number <b>88683539</b>
4. Generator's Phone ( <b>619 438-3321</b> )				B. State Generator's ID
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245 001</b>		C. State Transporter's ID <b>012455</b>
7. Transporter 2 Company Name		8. US F / A ID Number		D. Transporter's Phone <b>213 698-0991</b>
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD WHITTIER, CA 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>		E. State Transporter's ID
				F. Transporter's Phone
				G. State Facility's ID <b>CADDI41212451001</b>
				H. Facility's Phone <b>213 698-0991</b>
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No. Type	13. Total Quantity	14. Unit Wt./Vol.
a. HAZARDOUS WASTE SOLID ORM-E NA 9189 (EMPTY OPEN TOP DRUM)		1 DM		I. Waste No. State <b>512</b> EPA/Other <b>D001</b>
b. HAZARDOUS WASTE SOLID ORM-E NA 9189 (EMPTY CLOSED TOP DRUMS)		0104 DM	1001.60 P	State <b>512</b> EPA/Other <b>D001</b>
c. HAZARDOUS WASTE LIQUID ORM-E NA 9189 (WASTE FREON)		0101 DM	00050 G	State EPA/Other
d. HAZARDOUS WASTE LIQUID ORM-E NA 9189 (WATER - OIL) WASTE		003 DM	00160 G	State EPA/Other
J. Additional Descriptions for Materials Listed Above <b>B. ARE EMPTY DRUMS</b>		K. Handling Codes for Wastes Listed Above a. b. c. d. <b>01 01</b>		
15. Special Handling Instructions and Additional Information <b>PROFILE NUMBERS A11987, 11980, 12035, 11982</b>				
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; Or, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.				
Printed/Typed Name <b>Ronald Gaines</b>		Signature <b>Ronald Gaines</b> Month Day Year <b>05/11/90</b>		
TRANSPORTER 17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature <b>Javi Hernandez</b> Month Day Year <b>05/11/90</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature Month Day Year		
FACILITY 19. Discrepancy Indication Space				
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>FRANK FORD</b>		Signature <b>Frank Ford</b> Month Day Year <b>05/11/90</b>		

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 396 971</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>SIERRACIN MAGNEDYNE 2258 RUTHFORD RD., CARLSBAD, CA 92008</b>		A. State Manifest Document Number <b>88676998</b>				
4. Generator's Phone ( <b>619 438-3321</b> )		B. State Generator's ID				
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number: <b>CAD 042 245 001</b>	C. State Transporter's ID <b>012455</b>			
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone 213 698-0991			
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD WHITTIER, CA 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) <b>a. WASTE CORROSIVE LIQUID N.O.S NA 9193 (DEOXIDIZER)</b>		12. Containers No. <b>001 DM 000656 G</b>	13. Total Quantity	14. Unit Wt/Vol	15. Waste No. <b>133</b>	
b.					EPA/Other <b>D002</b>	
c.					State	
d.					EPA/Other	
e.					State	
f.					EPA/Other	
g.					State	
h.					EPA/Other	
j. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above <b>a. 01 b. c. d.</b>				
15. Special Handling Instructions and Additional Information <b>PROFILE NUMBER A11987</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>Ronald Gaines</b>		Signature <i>Ronald Gaines</i>	Month Day Year <b>05/22/90</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature <i>Javier Hernandez</i>	Month Day Year <b>05/22/90</b>			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature	Month Day Year			
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>FRANK FORD</b>		Signature <i>Frank Ford</i>	Month Day Year <b>10/5/22/90</b>			

Do Not Write Below This Line

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 396 971</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>STERRACIN/MAGNEDYNE 1258 RUTHFORD RD., CARLSBAD, CA 92008</b>		A. State Manifest Document Number <b>88681461</b>				
4. Generator's Phone <b>619 438-3321</b>		B. State Generator's ID				
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	C. State Transporter's ID <b>110237</b>			
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213 698-0991</b>			
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD WHITTIER, CA 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	Waste No.	
e. NAPHTHA WASTE, FLAMMABLE LIQUID UN 2553					State 213 EPA/Other F005	
b. WASTE PETROLEUM OIL, N.O.S, FLAMMABLE LIQUID, NA 1270 (WASTE OIL)		01/10DM	0015K0		State 221 EPA/Other D001	
c. WASTE M,E,K, FLAMMABLE LIQUID, UN 1193		001DM	0000K0		State 212 EPA/Other F003	
d. WASTE ACETONE, FLAMMABLE LIQUID, UN 1090		002DM	101110		State 212 EPA/Other F003	
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
		a.	b.	c.	d.	
15. Special Handling Instructions and Additional Information <b>PROFILE NUMBER B 10295,10298,10296,10297</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable International and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>Ron Gaines</b>		Signature <b>Ron Gaines</b>		Month Day Year <b>11/11/98 10</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name <b>Robert J CIRINCIONE</b>		Signature <b>Tall John</b>		Month Day Year <b>11/11/98 10</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name <b>John HALTE</b>		Signature <b>JH</b>		Month Day Year <b>11/12/98 10</b>		

88681461  
WITHIN CALIFORNIA CALL 1-800-862-7550

GENERATOR

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802

TRANSPORTER

FACILITY

Do Not Write Below This Line

White: TSDF SENDS THIS COPY TO DOHS WITHIN 30 DAYS

To: P.O. Box 1000 Sacramento, CA 95812

State of California  
Form Approved  
Printed or Printed

is—Health and Welfare Agency  
4MB No. 2050—0039 (Expires 9-30-91)  
or. (Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6  
and Front of Page 7

Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

<b>FORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 396 971</b>	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>S TERRACIN/MAGNEDYNE 2258 RUTHFORD RD ., CARLSBAD, CA 92008</b>		<p>A. State Manifest Document Number <b>88681463</b></p> <p>B. State Generator's ID</p>				
4. Generator's Phone (619) 438-3321						
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	<p>C. State Transporter's ID <b>1023</b></p> <p>D. Transporter's Phone <b>213 698-0991</b></p>			
7. Transporter 2 Company Name		8. US EPA ID Number	<p>E. State Transporter's ID</p> <p>F. Transporter's Phone</p>			
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD WHITTIER, CA 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>	<p>G. State Facility's ID <b>100091304501011</b></p> <p>H. Facility's Phone <b>213 698-0991</b></p>			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. HAZARDOUS WASTE LIQUID, NOS, ORM-E NA 9189 (FREON TF)		CAD 2 DM	01011110			State <b>211</b> EPA/Other <b>D001</b>
b.						State EPA/Other
c.						State EPA/Other
d.						State EPA/Other
J. Additional Descriptions for Materials Listed Above <b>A) FOR RECYCLE</b>		K. Handling Codes for Wastes Listed Above <b>a. C1 b.</b>				
15. Special Handling Instructions and Additional Information <b>PROFILE NUMBER B 10298</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>Ron Gaines</b>		Signature 		Month Day Year <b>11/11/98</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>ROBERT T CRINEON</b>		Signature 		Month Day Year <b>11/11/98</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>John HAGUE</b>		Signature 		Month Day Year <b>11/11/98</b>		

Do Not Write Below This Line

State of California  
Form Approved  
Please print or type




Health and Welfare Agency  
1. 2050-0039 (Expires 9-30-91)

Form designed for use on elite (12-pitch typewriter).

See Instructions on Back of Page 6  
and Front of Page 7

Department of Health Services  
Toxic Substances Control Division  
Sacramento, California

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>CAD 981 396 971</b>	Manifest Document No. <b>4515 4117</b>	2. Page 1 of <b>1</b>	Information in the shaded areas is not required by Federal law.	
3. Generator Name and Mailing Address <b>SIERRACIN MAGNEDYNE 2258 RUTHERFORD ROAD, CARLSBAD, CA. 92008</b>		A. State Manifest Document Number <b>88345415</b>				
4. Generator's Phone (619) 438-3321		B. State Generator's ID				
5. Transporter 1 Company Name <b>OMEGA RECOVERY SERVICES</b>		6. US EPA ID Number <b>CAD 042 245 001</b>	C. State Transporter's ID <b>208451</b>			
7. Transporter 2 Company Name		8. US EPA ID Number	D. Transporter's Phone <b>213/698-0991</b>			
9. Designated Facility Name and Site Address <b>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD. WHITTIER, CA. 90602</b>		10. US EPA ID Number <b>CAD 042 245 001</b>	E. State Transporter's ID			
			F. Transporter's Phone			
			G. State Facility's ID <b>CAD 041 245 15441</b>			
			H. Facility's Phone <b>213/698-0991</b>			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) <b>HAZARDOUS WASTE LIQUID N.O.S., ORM-E MAXXIM (Freon)</b>		12. Containers No. <b>0109</b>	13. Total Quantity <b>DIM 0.5495 G</b>	14. Unit Wt/Vol <b>State 211 EPA/Other F001</b>	I. Waste No.	
<b>b</b> WASTE PETROLEUM OIL N.O.S., COMBUSTIBLE LIQUID NA 1270		<b>0104</b>	<b>DIM 001200 G</b>	<b>State 221 EPA/Other D001</b>		
<b>c</b> WASTE NAPTHA, COMBUSTIBLE LIQUID , UN2553		<b>0101</b>	<b>DIM 010315 G</b>	<b>State 213 EPA/Other D001 Low Temp</b>		
<b>d</b> WASTE FLAMMABLE LIQUID N.O.S., UN 1993 (Coolant)		<b>0102</b>	<b>DIM 010185 G</b>	<b>State 214 EPA/Other D001</b>		
J. Additional Descriptions for Materials Listed Above <b>a.b.c.d.-Material for disposal</b>		K. Handling Codes for Wastes Listed Above a. <b>01</b> b. <b>01</b> c. <b>01</b> d. <b>01</b>				
15. Special Handling Instructions and Additional Information <b>Profile#B10295 B10299 B10298 B10295</b>		*Emergency#619/438-3321				
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>J.B. LEGRAN</b>		Signature 		Month Day Year <b>11/20/91</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>JAVIER HERNANDEZ</b>		Signature 		Month Day Year <b>11/20/91</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>John H. Hale</b>		Signature 		Month Day Year <b>11/20/91</b>		

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <u>CAD 981 396 971</u>	Manifest Document No. <u>415141118</u>	2. Page 1 of Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address  <u>SIEGRACIN MAGNEDYNE 2258 RUTHERFORD ROAD, CARLSBAD, CA. 92008</u>		A. State Manifest Document Number <u>88345418</u>			
4. Generator's Phone <u>(619) 438-3321</u>		B. State Generator's ID			
5. Transporter 1 Company Name <u>OMEGA RECOVERY SERVICES</u>		C. State Transporter's ID <u>208451</u>			
7. Transporter 2 Company Name		D. Transporter's Phone <u>213/698-0991</u>			
9. Designated Facility Name and Site Address  <u>OMEGA RECOVERY SERVICES 12504 E. WHITTIER BLVD. WHITTIER, CA. 90602</u>		10. US EPA ID Number <u>CAD 042 245 001</u>	E. State Transporter's ID		
			F. Transporter's Phone		
			G. State Facility's ID <u>CAD 01422145TA0411</u>		
			H. Facility's Phone <u>213/698-0991</u>		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a.  <u>WASTE OXIDIZER, CORROSIVE LIQUID N.O.S.</u> <u>NA 9193</u>		<u>003</u>	<u>DIM 001 140</u>	<u>G</u>	State <u>123</u> EPA/Other <u>D001</u>
b.					State
c.					EPA/Other
d.					State
					EPA/Other
J. Additional Descriptions for Materials Listed Above  <del>XXXXXXXXXXXXXX</del>		K. Handling Codes for Wastes Listed Above			
a.-Material for disposal		a. <u>O1</u>	b.	c.	d.
15. Special Handling Instructions and Additional Information  <u>Profile#B11787</u>					
*Emergency# <u>619/438-3321</u>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.  If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name <u>J.B. LEGRANT</u>		Signature 		Month Day Year <u>1/20/91</u>	
17. Transporter 1 Acknowledgement of Receipt of Materials  Printed/Typed Name <u>JAVIER HERNANDEZ</u> Signature  Month Day Year <u>1/20/91</u>					
18. Transporter 2 Acknowledgement of Receipt of Materials  Printed/Typed Name Signature  Month Day Year					
19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.  Printed/Typed Name <u>John H. Hale</u> Signature  Month Day Year <u>1/21/91</u>					

G E N E R A T O R	<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>C A D 9 8 2 3 5 6 9 3 3</b>	Manifest Document No. <b>090910</b>	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.	
	3. Generator's Name and Mailing Address <b>SIERRACIN TRANSFLEX 5600 BANDINI BLVD., BELL CA 90201</b>				A. State Manifest Document Number <b>871113498</b>		
	4. Generator's Phone (213) 269-9100				B. State Generator's ID <b>H A H Q 3 6 0 0 9 5 1 8</b>		
	5. Transporter 1 Company Name <b>VAN WATER &amp; ROGERS</b>		6. CAD US EPA ID Number <b>10801144</b>		C. State Trans. Order ID <b>905445</b>		
	7. Transporter 2 Company Name		8. US EPA ID Number		D. Transporter's Phone <b>(213) 269-9100</b>		
	9. Designated Facility Name and Site Address <b>OMEGA CHEMICAL COL 12504 E. WHITTIER BLVD., WHITTIER, CA 90602</b>		10. US EPA ID Number <b>C A D 0 4 2 2 4 5 0 0 1</b>		E. State Transporter's ID <b>C A D 0 4 2 2 4 5 0 0 1</b>		
	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	Type	F. Transporter's Phone <b>(213) 698-0991</b>		
	a. FREON - HAZARDOUS WASTE LIQUID N.O.S. ORM-A UN 1693		0 0 3	D M	G. State Facility's ID <b>C A D 0 4 2 2 4 5 0 0 1</b>		
	b.				H. Facility's Phone <b>(213) 698-0991</b>		
	c.						
d.							
J. Additional Descriptions for Materials Listed Above <b>FLOROCARBON 55-65% ETHANOL 30-35% SOLDER FLUX 5-10%</b>				K. Handling Codes for Wastes Listed Above a. <b>O1</b>			
L. Total Quantity 15. Special Handling Instructions and Additional Information				b.			
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.				c.			
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.				d.			
Printed/Typed Name <b>John McVay</b>		Signature <i>John McVay</i>		Month Day Year <b>07 01 88</b>			
Printed/Typed Name <b>MICHAEL STEVENSON</b>		Signature <i>michael Stevenson</i>		Month Day Year <b>10/21/1888</b>			
Printed/Typed Name		Signature		Month Day Year			
F A C I L I T Y		19. Discrepancy Indication Space					
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.							
Printed/Typed Name <b>John H. Acte</b>		Signature <i>John H. Acte</i>		Month Day Year <b>10/21/1888</b>			

If CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802; WITHIN CALIFORNIA CALL 1-800-852-7550

T R A N S P O R T E R

F A C I L I T Y

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>C A D 9 8 2 1 3 5 6 9 3 3 0 1 0 8 1 0</b>	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address  <b>SIERRACIN TRANSFLEX 5600 BANDINI BLVD., BELL, CA. 90201</b>		4. Generator's Phone (213) 269-9100		A. State Manifest Document Number <b>87113415</b>		
5. Transporter 1 Company Name  <b>VAN WALTERS + RYERS</b>		6. US EPA ID Number <b>F A D 0 0 9 2 3 0 2 4 4</b>	7. Transporter 2 Company Name		B. State Generator's ID <b>H A B C 2 6 0 0 9 5 1 8</b>	
		8. US EPA ID Number			C. State Transporter's ID <b>804025</b>	
9. Designated Facility Name and Site Address  <b>OMEGA CHEMICAL CO. 12504 E. WHITTIER BLVD. WHITTIER, CA. 90602</b>		10. US EPA ID Number <b>C A D 0 4 2 2 4 5 0 0 1</b>			D. Transporter's Phone <b>260-5217</b>	
					E. State Transporter's ID	
					F. Transporter's Phone	
					G. State Facility's ID <b>C A D 0 4 2 2 4 5 0 0 1</b>	
					H. Facility's Phone <b>513-698-0991</b>	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
a. FREON - HAZARDOUS WASTE LIQUID N.O.S. ORM-A UN1693		1	3 D M	1 1 1 5 1 0 G		State <b>.211</b> EPA/Other
b.		1	1	1		State EPA/Other
c.		1	1	1		State EPA/Other
d.		1	1	1		State EPA/Other
J. Additional Descriptions for Materials Listed Above  <b>FLOROCARBON 55 - 65% ETHANOL 30 - 35% SOLDER FLUX 5 - 10%</b>		K. Handling Codes for Wastes Listed Above a. <b>01</b>		b.	c.	d.
15. Special Handling Instructions and Additional Information						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>JOHN A. McVAY</b>		Signature <i>John McVay</i>		Month Day Year	10/13/1988	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>MICHAEL STEVENSON</b>		Signature <i>Michael Stevenson</i>		Month Day Year	10/13/1988	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>Henry R. Solomon</b>		Signature <i>Henry R. Solomon</i>		Month Day Year	10/21/1988	

Please print or type. (Form designed for use on elite (12-pitch typewriter).

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>C A D 0 6 7 7 3 7 2 2 1</b>	Manifest Document No. <b>01 01 01 31 6</b>	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.		
GENERATOR	3. Generator's Name and Mailing Address <b>SIERRACIN TRANSFLEX 5600 BANDINI BLVD., BELL, CA. 90201</b>	6. EPA ID Number <b>C A D 0 9 2 3 0 2 4 9</b>		A. State Manifest Document Number <b>87113406</b>			
	4. Generator's Phone (213) 269-9100	7. Transporter 1 Company Name <b>Van Water &amp; Rogers,</b>		8. US EPA ID Number		B. State Generator's ID	
TRANSPORTER	9. Designated Facility Name and Site Address <b>OMEGA CHEMICAL COMPANY 12504 E. WHITTIER BLVD., WHITTIER, CA. 90602</b>	10. US EPA ID Number <b>C A D 0 4 2 2 4 5 0 0 1</b>	12. Containers No.      Type		13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. WASTE TETRACHLOROETHYLENE ORM-A UN1897	01015 D M	010121715	G	State <b>NA</b>	EPA/Other <b>-211</b>	
FACILITY	b.				State		
	c.				State		
d.					State		
J. Additional Descriptions for Materials Listed Above <b>WASTE TETRACHLOROETHYLENE</b>				K. Handling Codes for Wastes Listed Above a. 01/F002 01 b. c. d.			
15. Special Handling Instructions and Additional Information <b>GLOVES AND GOGGLES</b>							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.							
Printed/Typed Name <b>John A. McVay</b>		Signature <i>JAMcVay</i>		Month	Day	Year	<b>09 16 87</b>
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name <b>Frank Arriola</b>		Signature <i>Frank Arriola</i>		Month	Day	Year	<b>10 91 6817</b>
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name		Signature		Month	Day	Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.							
Printed/Typed Name <b>J. Brent Oliver</b>		Signature <i>J. Brent Oliver</i>		Month	Day	Year	<b>10 91 6817</b>

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-324-8802; WITHIN CALIFORNIA CALL 1-800-852-7650

GENERATOR

TRANSPORTER

FACILITY

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No.	Manifest Document No.	2. Page _____ of _____	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address <b>SIERRACIN TRANSFLEX</b> 5600 BANDINI BLVD., BELL, CA. 90201		C A D 9 8 2 3 5 6 9 3 3	000616	A. State Manifest Document Number <b>87113418</b>		
4. Generator's Phone (213) 269-9100				B. State Generator's ID <b>HIA 01013610095118</b>		
5. Transporter 1 Company Name <b>Van Waters &amp; Rogers</b>		6. US EPA ID Number <b>CAD 0091230247</b>			C. State Transporter's ID <b>803160</b>	
7. Transporter 2 Company Name		8. US EPA ID Number			D. Transporter's Phone	
9. Designated Facility Name and Site Address Omega Chemical Co. 12504 E. Whittier Blvd., Whittier, CA. 90602		10. US EPA ID Number <b>CAD 042245001</b>			E. State Transporter's ID	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
a. FREON-HAZARDOUS WASTE LIQUID N.O.S. ORM-A UN1693		0 1 0 3	D M	1 1 5 0	G	State <b>211</b> EPA/Other
b.						State EPA/Other
c.						State EPA/Other
d.						State EPA/Other
13. Additional Descriptions for Materials Listed Above <b>FLUOROCARBON 55-65%</b> <b>ETHANOL 30-35%</b> <b>SOLDER FLUX 5-10%</b>				K. Handling Codes for Wastes Listed Above a. b. c. d.		
14. Special Handling Instructions and Additional Information						
15. Generator's Certification: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
I am a large quantity generator. I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>John McVay</b>		Signature <i>John McVay</i>		Month Day Year <b>10/16/88</b>		
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>Frank Areiola</b>		Signature <i>Frank Areiola</i>		Month Day Year <b>10/16/88</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19 Printed/Typed Name <b>John Solomon</b>						